## Fire Alarm System Log Book

The Chequered Flag 32 Borough Street Castle Donington Derby, DE74 2LA

Responsible Persons on Site: Ma.

MR. ROBERT.

ANTHONY SANDHAM.

J P Carty (Electrical Contractors) Limited
34 Borough Street
Castle Donington
Derby
DE74 2LA
Telephone: 01332 810773

This log book must be maintained by the responsible person(s) on site and must be available at all times together with the system operating keys.

Every "event" affecting the installation should be recorded, such as fire alarms, failures, tests, temporary disconnections, dates of installing engineers visits, and a note of any outstanding work or conditions.

DATE	TIME	ZONE	EVENT
9/8/19	11 AM		TEST FIRE ALARM PASSED. WA
9/8/19	11 AM	2	TEST FINE PLANT PASSED NR
11			BAL SMONE PAGE ND
•(			BAR CAU POINT PASS
N			CORRIDOR SMOKE PARS
a			KITCHEN SMORE PASS
N			KITCHEN CALL POINT PASS. SA
N			CLEMOED HEADS CROF 1550ED.
		j.i.	

## J P Carty (Electrical Contractors) Limited

### PATCERTIFICATE

Client:	Site: CHEQUERED FLAG						
Asset ID	Description	User	Test Instrument	Date	Retest Period	Next Test	-
001	Till	NREED	12E-0699	09/08/2019	12 Months	09/08/2020	Pass
002	FRIDGE KETTLE	NREED	12E-0699 12E-0699	09/08/2019	12 Months	09/08/2020	Pass

Total Tests: 3

Page 1

Contractor's Reference Number

**EMERGENCY LIGHTING PERIODIC** INSPECTION AND TESTING CERTIFICATE

COLL	actor	3 110	CICIL	e INU	IIIDEI

AND DESCRIPTION AND ADDRESS OF	
CRN/	•

DETAILS OF THE CLIENT

Occupier/ Client

The Chequered Flag

32 Borough Street, Castle Donington, Derby,

Derbyshire

Postcode DE74 2LA

PURPOSE OF CERTIFICATE

To certify continued compliance of an existing installation

<b>DETAILS OF THE EMERGENCY LIGI</b>	HTING INSTALLATION
--------------------------------------	--------------------

Address

32 Borough Street, Castle Donington, Derby, Derbyshire

Postcode DE74 2LA

installation covered by this

certificate

Extent of the Emergency lighting system only

CERTIFICATION

Contractor responsible for carrying out the inspection and testing (address)

34 Borough Street, Castle Donington, Derby

Postcode DE74 2LA

Trading title

J P Carty Electrical Contractors Lt

Telephone No 01332 810773

I/we hereby certify that the emergency lighting system installation at the above premises has been inspected and tested by me/us in accordance with the results of the items inspected and tested on page 2, and to the best of my/our knowledge and belief, the installation complies at the time of my/our inspection and testing with the appropriate recommendations and requirements given in BS 5266-1: 2016 Emergency lighting Part 1: Code of practice for the emergency lighting of premises, BS 1838: 2013 Lighting applications - Emergency lighting and BS EN 50172: 2004 / BS 5266-8: 2004 Emergency escape lighting systems, except for the deviations recorded.

(CAPITALS) NIGEL REED

Signature

Inspector

Date 09/08/2019

DETAILS OF DEVIATIONS FROM THE CURRENT CODE OF PRACTICE Details of deviations (Additional space to continue list is provided on page 3) Clause No

Ciduse 140.	betails of deviations (ridditional space to continue list is provided on page 5

Additional information has been supplied on page 3

Yes

No

RELATED REFERENCE DOCUMENTS

Electrical Installation Condition Report No. and/or date of most recent - covering the existing emergency lighting installation see Note.

Other documents (if any) please state

**NEXT INSPECTION** 

Note:

§ Enter interval in accordance with clause 7.2 of BS EN 50172: 2004 / BS 5266-8: 2004

We RECOMMEND that this installation is further inspected and

§ 12 months

tested after an interval of not more than

The wiring system of an existing emergency lighting system should have been periodically inspected and tested in accordance with BS 7671 and an Electrical Installation Condition Report issued. Where applicable and where available, the serial number and/or date of the most recent report should be recorded in the space provided.

Page 1 of []

This form is based on the model in Annex M of BS 5266: Part 1: 2016 Published by Certsure LLP. © Copyright Certsure LLP (June 2016)

Please see the 'Notes for Recipient' on the reverse of pages 1 and 2.

# Emergency Lighting Log Book

The Chequered Flag 32 Borough Street Castle Donington Derby DE74 2LA

This Log Book should be kept on the premises to which it relates in the care of a responsible person appointed by the Occupier/Owner of the premises

J P Carty (Electrical Contractors) Limited
34 Borough Street
Castle Donington
Derby
DE74 2LA

Telephone: 01332 810773

### Emergency Lighting

Number Type Lamp Size Location  61 BUCKAGO LEO BOUT  02 11 CORRIDOR.  03 N KITCREN.				
02 II CORRIDOR.	Number	Туре	Lamp Size	Location
	01	BUKAR	0 1 50	Bar
03 KITCHES.	02	"		CORRIDOR.
	03			KITCHE!

#### EXTINGUISHERS SUPPLIED New Chandon House, Lint 10 Westride Park, Dermore Way Flagranium, Durby DE21 7A2 TYPE / SIZE SSX/ 163494 for disper Metro 1. Ernel enterweet/ofean colum Websitt www.chean.colum SSX/163494 1 2500 CC/42 D.No. Contonen Name Total CHEQUIDED FERL CHETE RETER Address 32 Borrough STREET CASTIE DOUBLETON Ben SIGNAGE SUPPLIED **Email** FIFE EXT / CONSCINUAL Telephone No. FIRE ACTION Postcook DE74 24A DENTHUATION. CERTIFICATE OF CONFORMITY We hereby certify that the Fire Extinguishers as set out below have this day been maintained and passed satisfactory to 85 5305-3;2017 529 BUT HYDROS 2×6 602 Strvice Report and Advice is securitaria with 85 6366-32017 and 83 5366-3 2012 UNITS COMMISSIONED VARIATIONS FIRE BLANKET INSPECTION. YES. / NO REFILL DISCHARGE TEST/SUPPLY S/F period \$23 -00 Recommendations given da real constitute a regulatory Reform (Fire Safety) 2005 Risk Assessment DUTY OF CARE WASTE TRANSFER NOTE: Waste-Transfer Reg. No. C0.760985VG - Shi Reg. No. NGENEZI C10825 @ ALL Set unit @ INC per unit 1 APARIAL TIME 16 TO DEPARTURE TIME 16 30 DATE 5/9/13 per set CHEBUE NON-CONFORMING CIOTO CUSTOMER SIGNATURE TYPE W AF CO. OP FB HY AF OP H HR BACS AITN H per unit SIZE TECHNICAN SIGNATURE A- WIELD A- WESE SD: per and QTY. FB: per unit. QUOTATION - For acceptance please use contact details quoting Heterence Number: SSX/ 163494 ENVIRONMENTAL DISPOSAL वट प्रश्रो Ventiled Consumables Supplied HEAD O'RINGS per ont HORN/ELBOW "O" RINGS. per unit HOSE O' HINGS per unit GALIGE PATCHES cerunit SWETY PINS perunt OK' TAMPER PINS. per unit. TAMPER SEALS per unit. VALE 3 JATOY SUB TOTAL T Contomer Information on Estinguisher Maintenance and MSDS/COSHH TO CARRY FORWARD TOTAL \$23-00

500

distributed for the design of the same of the same and the same of the same of

### **Shop risk assessment**

Shop name: The chequered flag			Date of assessment: 12/08/2019				
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by who?	Action by when?	Done	
Slips and trips	Staff and customers may be injured if they trip over objects. In addition, they may be injured if they slip on spillages.	Staff mop up or report spillages.     Good hosekeeping					
Handling and moving stock	Staff risk injuries or back pain from handling heavy/bulky objects, eg deliveries of stock.	<ul> <li>Appropriate equipment is available to transport heavy items when moving stock and staff are trained in how to use it safely.</li> <li>Heavy goods are stored at a Managua or height</li> </ul>					
Working at height	Falls from any height can cause bruising and fractures.	<ul> <li>Staff are shown how to use a stable ladder/ other suitable device safely eg not to overreach, not to work on uneven floors.</li> <li>Only applicable re light bulbs and picture displays</li> </ul>					
Health of workers in the shop environment	All staff could be affected by factors such as:  • working conditions, eg hot/cold working temperatures, lack of welfare facilities or cramped conditions; or  • lack of job control, eg no control over timing of breaks, high volumes of customers during busy periods.	<ul> <li>Staff can speak confidentially to a supervisor or manager if they are feeling unwell or ill at ease because of work.</li> <li>Staff work maximum 4 hour shifts with a drinks break to be taken during slow trading</li> </ul>					
Threat of robbery and violence	Staff may suffer stress and/or injury from assaults, threats and abuse from members of the public.	<ul> <li>Staff report and take appropriate action on any incidents of abuse etc to manager for support/discussion.</li> <li>Access points are double locked and an alarm system is fittedSecurity cameras to be fitted first week of september</li> </ul>					
Fire		I have considered this and it doesn't apply to my shop.					


#### Shop risk assessment

What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by who?	Action by when?	Done
Shop equipment	Staff/customers could get electrical shocks or burns from using faulty electrical equipment, including portable electrical equipment – heaters, fans etc. Electrical faults can also lead to fires. Staff may also suffer injury from moving parts of equipment or unbalanced equipment.	All new equipment is checked before the first use to ensure that there are no obvious accessible dangerous moving parts, or the siting of the equipment does not cause additional hazards.      Staff are encouraged to spot and report any defective plugs, discoloured sockets, damaged cable and on/off switches.				
Cleaning	Staff risk skin irritation or eye damage from direct contact with cleaning chemicals. Vapour from cleaning chemicals may cause breathing problems.	Mops, brushes and protective gloves are provided and used.     Staff are shown how to use cleaning products safely.     Cleaning materials are properly stored.				
Young persons, disabled or pregnant workers	Some workers may be at a greater risk of harm from low risk hazards eg:  • young workers (under 18 years of age);  • disabled workers; and  • pregnant workers and nursing mothers.	<ul> <li>All staff to be aware that young colleagues may be inexperienced or lack awareness of risks.</li> <li>Procedures are in place to protect young people, who might be more susceptible to certain risks, eg lack of maturity to deal with aggressive customers.</li> <li>Manager agrees action plan to address any specific needs.</li> </ul>				


It is important you discuss your assessment and proposed actions with staff or their representatives.

You should review your risk assessment if you think it might no longer be valid (eg following an accident in the workplace) or if there are any significant changes to the hazards in your shop, such as new work equipment or work activities.











Intruder Alarm System Information Log Book

Elite Security Services Ltd

9 Mallard Way, Pullman Business Park

Pride Park

Derby DE24 8GX

Contract No. F6120

Office Hours Telephone No. 01332 383630

Out of Hours No. 0844 335 2047

Abort No. 0800 716460

PLEASE KEEP THIS LOG BOOK IN THE PLASTIC WALLET ATTACHED

TO YOUR CONTROL PANEL.

FOR FAULTS IT HELPS TO CALL BEFORE 10AM

